

Parker LORD Aerospace MRO Services

2022 Rotary-Wing Capabilities

For Pricing Contact:
repairstation@parker.com

	OEM P/N	Parker LORD P/N	PART DESCRIPTION	CONDITION TYPE
AIRBUS AS350 / EC 130				
New Offering	704A33-633-211	704A33-633-211LORD	Main Rotor Spherical Bearing / Spherical Stop	New-PMA
BELL 204, 205, 212				
	204-031-920-003	J-9797-6	Pylon Friction Damper Assembly	Overhaul Exchange
	204-031-920-003	J-16656-1	Pylon Friction Damper Assembly Repair Kit	New-PMA
	204-031-920-003	J-9993-3	Boot For Pylon Friction Damper Assy	New-PMA
	204-031-927-005	J-8085-6	Fifth Mount, Transmission	Overhaul Exchange
	204-031-927-007	J-8085-8	Mount, Transmission	Overhaul Exchange
Now EASA Approved	204-310-101-101	LORD 204-310-101101	Tension Torsion (TT) Strap	New-PMA
	212-030-273-001	J-14105-1	Cap Landing Gear Assy, Forward	Overhaul Exchange
	212-030-274-001	J-14106-1	Cap Landing Gear Assy, Aft	Overhaul Exchange
	212-030-436-007	J-15452-3	FWD Cap, Landing Gear	Overhaul Exchange
	212-030-437-007	J-15452-4	AFT Cap, Landing Gear	Overhaul Exchange
BELL 206				
	206-011-139-001	J-14258-3	Arm Assy (Flap Restraint)	Overhaul Exchange
	206-030-539-101	LB9-1301-1-1	Isolation Mount (Pylon)	Overhaul Exchange
	206-030-539-101	LB9-1301-1-1VFM	Isolation Mount, KAflex Mod	Overhaul Exchange
	206-033-501-001	LB1-1010-4-1	Nodal Beam Support (Forward)	Overhaul
	206-033-501-003	LB1-1010-6-1	Nodal Beam Support, LH Aft	Overhaul Superseded by 206-033-501-101
	206-033-501-004	LB1-1010-6-2	Nodal Beam Support, RH Aft	Overhaul Superseded by 206-033-501-102
	206-033-501-101	LB1-1010-22-1	Nodal Beam Support, LH Aft	Overhaul
	206-033-501-102	LB1-1010-22-2	Nodal Beam Support, RH Aft	Overhaul
	206-033-506-101	J-15413-17	Restraint, Transmission	Upgradable to 206-033-506-107
	206-033-506-107	J-15413-20	Restraint, Transmission	Overhaul Exchange
	206-033-506-107	J-15413-20	Restraint, Transmission	Repair
	206-033-506-109	J-15413-21	Restraint, Transmission	Overhaul Exchange
	206-033-506-109	J-15413-21	Restraint, Transmission	Repair
	206-033-516-101	LB9-1010-1-2	Flexure Assy, Nodal Beam	Overhaul Exchange
	206-033-518-005	J-15424-2	Stop Assy (Upstop)	Overhaul Exchange
	206-033-518-007	J-15425-2	Stop Assy (Downstop)	Overhaul Exchange
	206-033-544-001	LB9-1010-8-1	Support Assy, Restraint	Overhaul
New Offering	206-033-545-001	LB9-1010-7-1	Elastomeric Bearing for 206-033-544-001	New-PMA
	206-033-554-101	LB6-1010-16-1	Pylon Link Assy	Overhaul Exchange
Now EASA Approved	206-310-004-101	LORD206-310-004101	Tension Torsion (TT) Strap	New-PMA(STC)
Now EASA Approved	206-310-004-103	LORD206-310-004103	Tension Torsion (TT) Strap	New-PMA(STC)



ENGINEERING YOUR SUCCESS.

Parker LORD Aerospace MRO Services

2022 Rotary-Wing Capabilities

For Pricing Contact:
repairstation@parker.com

	OEM P/N	Parker LORD P/N	PART DESCRIPTION	CONDITION TYPE
BELL 206				
Now EASA Approved	Replaces: one 206-011-812-005, two B-2012, two 53642-75, two 206-411-814-003, two 206-011-862-001	LB2-1010-20-1	Elastomeric TR Trunnion Kit	New-PMA(STC)
Now EASA Approved	Replaces: one 206-011-812-005, two B-2012, two 53642-75, two 206-411-814-003, two 206-011-862-001	LB2-1010-20-2	Elastomeric TR Trunnion Bearing	New-PMA(STC)
BELL 214				
	214-010-158-001	LB1-1003-1-1	Bearing Assy, Flapping	Overhaul Exchange
	214-030-614-003	LB9-1004-15-3	Torsion Arm Assy, Pylon Support, LH	Overhaul Exchange
	214-030-614-004	LB9-1004-15-4	Torsion Arm Assy, Pylon Support, RH	Overhaul Exchange
	214-030-615-003	LB9-1004-3-3	Clevis Assy, Pylon Support, LH	Overhaul Exchange
	214-030-615-004	LB9-1004-3-4	Clevis Assy, Pylon Support, RH	Overhaul Exchange
	214-031-612-115	J-17746-5	Spring, Elastomeric, Fwd and Aft	Overhaul Exchange
	214-031-614-105	LB9-1004-29-7	Arm Assy, LH	Overhaul Exchange
	214-031-614-107	J-16644-5	Plate Assy	Overhaul Exchange
	214-031-614-108	J-16644-6	Plate Assy	Overhaul Exchange
	214-031-614-125	LB9-1004-29-14	Arm Assy, RH	Overhaul Exchange
	214-031-614-127	J-16644-17	Plate Assy	Overhaul Exchange
	214-031-614-128	J-16644-18	Plate Assy	Overhaul Exchange
	214-031-615-105	LB9-1004-20-9	Clevis Assy, LH	Overhaul Exchange
	214-031-615-106	LB9-1004-20-10	Clevis Assy, RH	Overhaul Exchange
	214-031-617-113	LB9-1004-45-1	Spring	Overhaul Exchange
BELL 222 / 230				
	222-031-605-109	LB9-1302-5-1	Flexure Assy	Overhaul
	222-331-617-103	LB1-1302-4-2	Isolation Mount, Lateral	Overhaul Exchange
	222-331-618-105	LB1-1302-3-1	Isolation Mount, Longitudinal	Overhaul Exchange
BELL 407				
	407-310-100-105	J-17750-24	Main Rotor Hub Damper	Overhaul Exchange
	407-310-100-107	J-17750-25	Main Rotor Hub Damper (Blue Coat)	Overhaul Exchange
SPEIIA-equipped part	407-310-101-101	LB9-1232-4-1	Shear Bearing	Overhaul Exchange
SPEIIA-equipped part	407-310-101-105	LB9-1232-6-1	Shear Bearing (Blue Coat)	Overhaul Exchange
SPEIIA-equipped part	407-310-102-101	LB4-1232-3-1	Lead Lag Bearing	Overhaul Exchange
SPEIIA-equipped part	407-310-102-103	LB4-1232-7-1	Lead Lag Bearing (Blue Coat)	Overhaul Exchange
	407-310-203-101	LB1-1232-5-1	Corner Mount	Overhaul Exchange
	407-312-100-101	LB2-1232-1-1	Tail Rotor Flapping Bearing	Overhaul Exchange
BELL 412				
	204-031-920-003	J-9797-6	Pylon Friction Damper Assembly	Overhaul Exchange
	204-031-920-003 (Repair Kit)	J-16656-1	Pylon Friction Damper Assembly Repair Kit	New-PMA
	204-031-920-003	J-9993-3	Boot For Pylon Friction Damper Assy	New-PMA
	204-031-920-003	J-9994-1	Housing for Damper Assy	New-PMA



ENGINEERING YOUR SUCCESS.

Parker LORD Aerospace MRO Services

2022 Rotary-Wing Capabilities

For Pricing Contact:
repairstation@parker.com

	OEM P/N	Parker LORD P/N	PART DESCRIPTION	CONDITION TYPE
BELL 412				
	204-031-920-003	Y-16960-3-1	Inner Member for Damper Assy	New-PMA
	204-031-927-107	J-8085-50	Mount, Transmission	Overhaul Exchange
	212-030-436-007	J-15452-3	FWD Cap, Landing Gear	Overhaul Exchange
SPEIIA-equipped part	412-010-106-101	REP412-010-106-101	Pivot Bearing	Repair Exchange
Upgrade Available	412-010-145-105	J-16663-4	Damper Yoke Set (Qty 4) ▽▽	Overhaul Exchange
▲	412-310-146-103	J-16663-7	Damper Yoke Set (Qty 4)	Overhaul Exchange
SPEIIA-equipped part	412-010-190-103	LB9-1062-8-2N	Spindle Assembly ▽ ▽	Overhaul
SPEIIA-equipped part	412-010-190-105	LB9-1062-18-1N	Spindle Assembly ▽ ▽	Overhaul
	412-030-437-103	J-16883-2	Aft Landing Gear Cap Assy	Overhaul Exchange
	412-330-437-101	J-16883-9	Aft Landing Gear Cap Assy	Overhaul Exchange
Upgrade Available	412-330-437-103	J-23381-5	Aft Landing Gear Cap Bumper Pad ▽▽▽	Overhaul Exchange
Fluid Resistant	412-330-437-107	J-23381-7	Rubber Bumper (New Design)	Overhaul Exchange
Fluid Resistant	412-330-437-105	J-16883-10	Aft Landing Gear Cap Assembly (New Design)	Overhaul Exchange
Fluid Resistant	412-340-102-101	412-340-102-101	Main Driveshaft Boot	New-PMA
Fluid Resistant	412-340-102-101	REP412-340-102-101	Main Driveshaft Boot	Overhaul Exchange
BELL 427				
SPEIIA-equipped part	407-310-100-107	J-17750-25	Main Rotor Hub Damper (Blue Coat)	Overhaul Exchange
SPEIIA-equipped part	407-310-101-107	LB9-1232-6-2	Shear Bearing	Overhaul Exchange
SPEIIA-equipped part	407-310-102-101	LB4-1232-3-1	Lead Lag Bearing	Overhaul Exchange
SPEIIA-equipped part	407-310-102-103	LB4-1232-7-1	Lead Lag Bearing (Blue Coat)	Overhaul Exchange
SPEIIA-equipped part	407-312-100-101	LB2-1232-1-1	Tail Rotor Flapping Bearing	Overhaul Exchange
SPEIIA-equipped part	427-310-201-103	FL-1044-3	LIVE Mount	Overhaul Exchange
BELL 429				
	427-310-201-107	FL-1087-4	LIVE Mount	Overhaul Exchange
Upgrade Available	429-310-001-105	J-23813-2	Lead-Lag Damper	Overhaul Exchange
▲	429-310-001-109	J-23813-4	Lead-Lag Damper	Overhaul Exchange
Upgrade Available	429-310-003-101	LB4-1274-4-1	CF Bearing (Blue Coat)	Overhaul Exchange
▲	429-310-003-103	LB4-1274-5-1	CF Bearing (Blue Coat)	Overhaul Exchange
	429-310-201-105	J-23823-12	Pitch Restraint Spring Assembly	Overhaul Exchange
BELL 430				
	430-310-101-107	LB9-1220-2-5	Shear Restraint ▽	Exchange
	430-310-101-107	LB9-1220-2-5	Shear Restraint ▽	Overhaul
	430-310-104-105	FL-1030-8	Damper, Blade Set (Qty 2)	Rebuild Exchange
	430-310-200-107	FL-1027-7	LIVE Mount ▽	Overhaul



ENGINEERING YOUR SUCCESS.

Parker LORD Aerospace MRO Services

2022 Rotary-Wing Capabilities

For Pricing Contact:
repairstation@parker.com

OEM P/N	Parker LORD P/N	PART DESCRIPTION	CONDITION TYPE
MD 500 / 520			
369A1724-7	LB2-1056-17-1	Bearing (Tail Rotor Teetering)	New-PMA
369D21400-503	J-15640-6	Main Rotor Damper	New-PMA
369D21721-21	369D21721-21	Fork Assy (Tail Rotor)	Overhaul
SCHWEIZER 300 / 330			
269A1290-003	J-15640-14	Main Rotor Damper	New-PMA

- ▼ Life-limited part.
- ▼ LORD can upgrade the LB9-1062-8-2N (412-010-190-103) to the LB9-1062-18-1N (412-010-190-105)
- ▼ LORD can upgrade the J-16663-4 (412-010-145-105) to the J-16663-7 (412-310-146-103)
- ▼ LORD can upgrade the J-23381-5 (412-330-437-103) to the J-23381-7 (412-330-437-107)

© 2022 Parker Hannifin

Information and specifications subject to change without notice and without liability therefor. Trademarks used herein are the property of their respective owners.

PB6077 OD 04/22 Rev.21

Parker LORD
Engineered Materials Group
111 LORD Drive
Cary, NC 27511-7923
USA

Customer Support Center (in United States & Canada)
+1 877 ASK LORD (275 5673)
lord.com/mro
Email: customer.support@parker.com; repairstation@parker.com

Parts handled directly by Parker LORD
may be shipped DDP to:
Parker LORD Corporation
Attn: Repair Station
2455 Robison Road West
Erie, PA 16509 USA
repairstation@parker.com



ENGINEERING YOUR SUCCESS.